



Fair Price Report  
real repair records, not a labor  
guide

Report FPR-a4138d8d8992

Issued October 2, 2026

Data as of July 2026

[fixdozer.com/repair-cost/chevrolet/silverado-1500/thermostat-replacement/](https://fixdozer.com/repair-cost/chevrolet/silverado-1500/thermostat-replacement/)

## Chevrolet Silverado 1500 — Thermostat Replacement


What owners actually paid for this repair, computed from **real, paid Chevrolet Silverado 1500 thermostat replacements** at independent shops across the US.

**\$286**

typical total — half of all Chevrolet Silverado 1500 thermostat replacement jobs cost less, half cost more

Fair range **\$180 – \$434**

the middle half of all invoices  
(parts + labor + fees)



| LINE ITEM                                                                                                                         | LOW (1 IN 4 PAID LESS) | TYPICAL      | HIGH (3 IN 4 PAID LESS) |
|-----------------------------------------------------------------------------------------------------------------------------------|------------------------|--------------|-------------------------|
| <b>Parts — Thermostat</b><br>Thermostat (often with housing on newer engines), gasket, coolant                                    | \$24                   | <b>\$63</b>  | \$104                   |
| <b>Labor — 1.7 hrs typical</b><br>Range 1.2 – 2.3 hrs: drain, replace thermostat or housing, refill and bleed, verify temperature | \$108                  | <b>\$174</b> | \$261                   |
| <b>Shop fees, supplies &amp; tax</b><br>The remainder of a typical invoice after parts and labor; varies by state and shop        | —                      | <b>~\$49</b> | —                       |
| <b>Total — what owners paid</b>                                                                                                   | <b>\$180</b>           | <b>\$286</b> | <b>\$434</b>            |

Low / typical / high are computed per line, so they don't add up exactly to the totals — the total row is the real distribution of complete invoices.

### IS YOUR QUOTE FAIR?

A quote between **\$180 and \$434** is inside the band where half of all Chevrolet Silverado 1500 thermostat replacements landed. Below it is not automatically a bargain (a stand-alone thermostat with a gasket); above it is not automatically gouging (an integrated thermostat-housing assembly, coolant flush, access under the intake) — but both ends deserve a question.

### WHAT MOVES THE PRICE

- **Thermostat or housing** — many newer engines sell the thermostat only as part of a plastic housing.
- **Access** — some are on top; some live under the intake.
- **Coolant** — a full refill with the specified coolant is part of the job.

### ABOUT THIS DATA · HOW TO USE THIS REPORT

Vehicle **Chevrolet Silverado 1500, model years 1998–2023**  
Data confidence **High** — *large sample, stable ranges*  
Records through **July 2026**, refreshed continuously  
Source **paid invoices from independent US repair shops**

Bring it to the shop. Ask for the written estimate split into parts, labor hours and rate, and fees — then compare each line. A shop that explains a number above the range is doing its job; one that won't is telling you something too.

**NOT A QUOTE** This report describes what other owners paid for the same repair. Your year, engine, region and the parts chosen shift the number. FixDozer does not perform repairs and receives nothing from shops.

© 2026 FixDozer · [fixdozer.com](https://fixdozer.com)