



Chevrolet Malibu — Control Arm Replacement

What owners actually paid for this repair, computed from **real, paid Chevrolet Malibu control arm replacements** at independent shops across the US.

\$523

typical total — half of all Chevrolet Malibu control arm replacement jobs cost less, half cost more

Fair range **\$349 – \$701**

the middle half of all invoices
(parts + labor + fees)



LINE ITEM	LOW (1 IN 4 PAID LESS)	TYPICAL	HIGH (3 IN 4 PAID LESS)
Parts — Control arm(s)	\$161	\$225	\$321
Control arm(s) with bushings and ball joint where integral			
Labor — 2.4 hrs typical	\$142	\$212	\$299
Range 1.7 – 3.3 hrs: replace the arm(s), torque to spec, alignment			
Shop fees, supplies & tax	—	~\$86	—
The remainder of a typical invoice after parts and labor; varies by state and shop			
Total — what owners paid	\$349	\$523	\$701

Low / typical / high are computed per line, so they don't add up exactly to the totals — the total row is the real distribution of complete invoices.

IS YOUR QUOTE FAIR?

A quote between **\$349 and \$701** is inside the band where half of all Chevrolet Malibu control arm replacements landed. Below it is not automatically a bargain (one lower arm on an accessible layout); above it is not automatically gouging (both sides, upper and lower arms, aluminum OEM arms, alignment included) — but both ends deserve a question.

WHAT MOVES THE PRICE

- **One arm or a pair** — bushings wear in pairs; doing both sides avoids a second alignment.
- **Integral ball joint** — arms with the joint built in cost more but replace two wear items at once.
- **Alignment** — required after arm replacement — expect it on the invoice.

ABOUT THIS DATA · HOW TO USE THIS REPORT

Vehicle **Chevrolet Malibu, model years 1997–2023**
Data confidence **Good** — *good sample, dependable ranges*
Records through **July 2026**, refreshed continuously
Source **paid invoices from independent US repair shops**

Bring it to the shop. Ask for the written estimate split into parts, labor hours and rate, and fees — then compare each line. A shop that explains a number above the range is doing its job; one that won't is telling you something too.

NOT A QUOTE This report describes what other owners paid for the same repair. Your year, engine, region and the parts chosen shift the number. FixDozer does not perform repairs and receives nothing from shops.