



Fair Price Report
real repair records, not a labor
guide

Report FPR-cf31679803ba

Issued September 2, 2026

Data as of July 2026

fixdozer.com/repair-cost/chevrolet/silverado-1500/ac-condenser-replacement/

Chevrolet Silverado 1500 — AC Condenser Replacement

What owners actually paid for this repair, computed from **real, paid Chevrolet Silverado 1500 AC condenser replacements** at independent shops across the US.

\$817

typical total — half of all Chevrolet Silverado 1500 AC condenser replacement jobs cost less, half cost more

Fair range **\$654 – \$1,016**

the middle half of all invoices
(parts + labor + fees)



LINE ITEM	LOW (1 IN 4 PAID LESS)	TYPICAL	HIGH (3 IN 4 PAID LESS)
Parts — A/C condenser Condenser with new receiver-drier, o-rings and refrigerant	\$229	\$283	\$355
Labor — 3.9 hrs typical Range 2.8 – 5.2 hrs: recover refrigerant, remove front fascia or grille as needed, swap condenser and drier, evacuate, recharge, leak-check	\$330	\$444	\$596
Shop fees, supplies & tax The remainder of a typical invoice after parts and labor; varies by state and shop	—	~\$91	—
Total — what owners paid	\$654	\$817	\$1,016

Low / typical / high are computed per line, so they don't add up exactly to the totals — the total row is the real distribution of complete invoices.

IS YOUR QUOTE FAIR?

A quote between **\$654 and \$1,016** is inside the band where half of all Chevrolet Silverado 1500 AC condenser replacements landed. Below it is not automatically a bargain (aftermarket condenser with the drier reused, charge only topped off); above it is not automatically gouging (bumper cover removal on newer models, R-1234yf refrigerant, damaged lines replaced at the same time) — but both ends deserve a question.

WHAT MOVES THE PRICE

- **Front-end access** — many newer vehicles need the bumper cover off to reach the condenser.
- **Refrigerant type** — R-1234yf systems charge at several times the R-134a price.
- **Collateral damage** — road debris that killed the condenser often nicked lines or the radiator too.

ABOUT THIS DATA · HOW TO USE THIS REPORT

Vehicle **Chevrolet Silverado 1500, model years 1999–2023**
Data confidence **High** — *large sample, stable ranges*
Records through **July 2026**, refreshed continuously
Source **paid invoices from independent US repair shops**

Bring it to the shop. Ask for the written estimate split into parts, labor hours and rate, and fees — then compare each line. A shop that explains a number above the range is doing its job; one that won't is telling you something too.

NOT A QUOTE This report describes what other owners paid for the same repair. Your year, engine, region and the parts chosen shift the number. FixDozer does not perform repairs and receives nothing from shops.

© 2026 FixDozer · fixdozer.com