



Fair Price Report
real repair records, not a labor
guide

Report FPR-c387e969caf5

Issued September 2, 2026

Data as of July 2026

fixdozer.com/repair-cost/chevrolet/silverado-1500/headlight-assembly-replacement/

Chevrolet Silverado 1500 — Headlight Assembly Replacement


What owners actually paid for this repair, computed from **real, paid Chevrolet Silverado 1500 headlight assembly replacements** at independent shops across the US.

\$143

typical total — half of all Chevrolet Silverado 1500 headlight assembly replacement jobs cost less, half cost more

Fair range **\$80 – \$254**

the middle half of all invoices
(parts + labor + fees)



LINE ITEM	LOW (1 IN 4 PAID LESS)	TYPICAL	HIGH (3 IN 4 PAID LESS)
Parts — Headlight assembly Complete headlight housing (bulbs may transfer or be new)	\$19	\$28	\$75
Labor — 1 hrs typical Range 0.5 – 1.5 hrs: remove bumper cover or grille as needed, swap the assembly, aim the beam	\$42	\$69	\$130
Shop fees, supplies & tax The remainder of a typical invoice after parts and labor; varies by state and shop	—	~\$46	—
Total — what owners paid	\$80	\$143	\$254

Low / typical / high are computed per line, so they don't add up exactly to the totals — the total row is the real distribution of complete invoices.

IS YOUR QUOTE FAIR?

A quote between **\$80 and \$254** is inside the band where half of all Chevrolet Silverado 1500 headlight assembly replacements landed. Below it is not automatically a bargain (aftermarket halogen housing on an older vehicle, easy access); above it is not automatically gouging (OEM LED assembly, bumper removal required, both sides replaced for matching) — but both ends deserve a question.

WHAT MOVES THE PRICE

- **Halogen vs. LED** — LED and adaptive assemblies cost multiples of a halogen housing.
- **Access** — many vehicles need the bumper cover off.
- **Pairs** — a new housing next to a hazed one looks mismatched — many owners do both.

ABOUT THIS DATA · HOW TO USE THIS REPORT

Vehicle **Chevrolet Silverado 1500, model years 1999–2023**
Data confidence **Good** — *good sample, dependable ranges*
Records through **July 2026**, refreshed continuously
Source **paid invoices from independent US repair shops**

Bring it to the shop. Ask for the written estimate split into parts, labor hours and rate, and fees — then compare each line. A shop that explains a number above the range is doing its job; one that won't is telling you something too.

NOT A QUOTE This report describes what other owners paid for the same repair. Your year, engine, region and the parts chosen shift the number. FixDozer does not perform repairs and receives nothing from shops.

© 2026 FixDozer · fixdozer.com